

General Environmental Incident Summary

Incident: 4137 **Date/Time Notice:** 6/16/2016 1400 **DEM Incident No:**
Responsible Party: United Quality Cooperative
Date Incident: 6/15/2016 **Time Incident:** 2230 **Duration:** 5 minutes
County: McKenzie **Twp:** 151 **Rng:** 96 **Sec:** 3 **Qtr:**
Lat: 47.92872 **Long:** -102.94290 **Method:** Interpolation from map
Location Description: Keene Cenex Store
207 West Main St.
Keene, ND 58847
Submitted By: Nathan Aucker **Affiliation:** CHS Safety Consultant
Address: 307 Main St.
City: New Town **State:** ND **Zip:** 58763

Received By:

Contact Person: Cameron Erickson
307 Main St.
New Town , ND 58763

Distance Nearest Occupied Building: 150 Feet **Release Contained:** Yes

Type of Incident: Unattended Fuel pump

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 70.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Customer was fueling the semi truck and climbed back into his cab and did not notice that the fuel nozzle had come out of the fuel tank.

Risk Evaluation:

N/A

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Any soil that was contaminated was removed from the site and was disposed of at a approved facility. Documentation of the disposal will be sent to the department of health as soon as it is received from the facility.

Action Taken or Planned:

The spill was contained on the pavement area and flowed to a lower parking area as shown on the facility map. Soil that was contaminated at the parking area was removed and disposed of at a approved facility.

Wastes Disposal Location: Awaiting notification from the agreed upon disposal location.

Agencies Involved: NDDDES, Local Law Enforcement

Updates

Date: 6/16/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 6/27/2016 **Status:** No Further Action Requested

Author: Tintes Schiwal, Emily

Updated Volume:

Notes:

While fueling a truck, the driver spilled diesel on the property and then left the scene. Because they don't know who the responsible party is, CHS is taking responsibility for the cleanup of their own property. I spoke to a company representative the morning after the spill, and he said the spill area was approximately 30' X 375' and about 60-80 gallons. CHS hired a contractor to excavate the contaminated soils the morning after the spill was discovered. They said they dug down approximately 6" in most areas, but they dug down 12" in one area with scoria where the diesel seemed to have seeped deeper. They took the soils to the Secure Energy landfill and provided us with the landfill tickets to demonstrate this. They also provided us with photos of the spill site and cleanup. All documentation can be found in the corresponding folder.